


# ELECTRICAL SAFETY RECALL

## RYOBI Airwave 40L 1.8HP Upright Air Compressor

### Model RA-ACDDU1840



#### IDENTIFICATION:

The Ryobi 40 Litre 1.8HP Oil Free Direct Drive Upright Air Compressor RA-ACDDU1840 was sold through Bunnings Warehouse stores and online at [www.bunnings.com.au](http://www.bunnings.com.au) between 2 February 2015 and 2 February 2020.

#### DEFECT:

There is inadequate insulation on the wiring to the overload switch under the compressor. This is accessible to the user; if the user reaches into the cavity of the compressor body they may have access to live parts.

#### HAZARD

RISK OF ELECTRIC SHOCK

#### ACTION REQUIRED:

1. Consumers should immediately stop using the RYOBI compressor and unplug the RYOBI compressor from mains power.
2. When possible please return the product to a Bunnings store to obtain either:
  - a. a replacement new version of the product (once it becomes available); or
  - b. a full refund of the purchase price paid for the product.

### For further information

Please direct all calls and any queries concerning this recall to **Techtronic Industries Australia Pty Limited's product service team** on **1300 859 017**, or email [recall@ryobi.com.au](mailto:recall@ryobi.com.au), [www.ryobi.com.au](http://www.ryobi.com.au)

See [www.productsafety.gov.au](http://www.productsafety.gov.au) for Australian product recall information.