


# Voluntary Product Safety Recall

See [www.recalls.gov.au](http://www.recalls.gov.au) for Australian Product Recall Information

**Techtronic Industries Australia Pty Ltd is conducting a voluntary product recall.**

The Products that are subject of the recall are the RYOBI Petrol Line Trimmer/ Brushcutter Model Nos. RBC254FSDSN, RBC254FSBSN, ABCLT04G and Homelite Petrol Line Trimmer / Brushcutter HBC25SJSN (all include Blade attachment RAC1101 or LTA024) (RBC254FSDSN is pictured below):



The Product has been sold through Bunnings retailers throughout Australia from September 2013 to April 2016.

**What is the Problem?** The Product is being recalled because if the nut securing the Blade is not properly tightened before use, in accordance with the instructions, the Blade may detach.

**What is the Risk?** If the Blade detaches during use, this poses a risk of laceration to consumers.

**What to do:** We kindly ask that you immediately stop using the Blade attachment and to contact Techtronic Industries Australia Pty Limited by telephone, email or via post at the address below. Techtronic Industries Australia Pty Limited will advise you how to proceed with your options in respect of the Product and the Blade. Your options are:

1. to return the Product (as a whole) for a refund of the full purchase price of the Product; or
2. to return the Blade (only) for a refund of the full retail price of the Blade.

**Contact Details:** Contact Techtronic Industries Australia Pty Limited's product service on 1300 859 017 (Freecall), mail PO Box 2179 Rowville VIC 3178, or email [info@ryobi.com.au](mailto:info@ryobi.com.au), or see the website: [www.ryobi.com.au](http://www.ryobi.com.au). We apologise to Bunnings and its customers for any inconvenience caused.

**See [www.recalls.gov.au](http://www.recalls.gov.au) for Australian Product Recall Information**